



**OHIO TURNPIKE AND  
INFRASTRUCTURE COMMISSION**

**ADDENDUM NO. 1**  
**ISSUED: MAY 19, 2023**

**To**

**LOI NO. 8-2023**

**REQUEST FOR LETTERS OF INTEREST (LOIs) FOR PROFESSIONAL ENGINEERING  
SERVICES PROJECT NO. 71-23-06**

**ISSUED: APRIL 28, 2023**

**LETTERS OF INTEREST DUE DATE: 5:00 P.M. (Eastern) ~~MAY 19, 2023~~ MAY 24, 2023**

**ATTENTION OF RESPONDENTS IS DIRECTED TO:**

**ANSWERS TO QUESTIONS RECEIVED THROUGH 5:00 PM ON MAY 12, 2023:**

**-AND-**

**2022 OTIC Bridge Inspection Reports for: MP 56.1, 56.3, and 58.5  
For Reference Only**

**-AND-**

**PROPOSAL DUE DATE EXTENDED TO 5:00 P.M. (EASTERN TIME), MAY 24, 2023**

Issued by the Ohio Turnpike and Infrastructure Commission through Aimee W. Lane, Esq., Director of  
Contracts Administration

*Aimee W. Lane*

\_\_\_\_\_  
Aimee W. Lane, Esq.,  
Director of Contracts Administration

May 19, 2023  
Date

**ANSWERS TO QUESTIONS RECEIVED THROUGH 5:00 P.M. ON MAY 12, 2023:**

**Q#1 Are existing plans available at this time? How can they be obtained?**

*A#1 Original and rehabilitation plan sets are available upon written request by e-mail to [purchasing@ohioturnpike.org](mailto:purchasing@ohioturnpike.org) and due to size, an FTP link will be sent by e-mail to those firms making a request.*

**Q#2 To what extent is MP 56.1 and MP 58.5 to be widened?**

*A#2 Bridges will be widened to accommodate future third lane widening projects. Extents to be determined in Bridge Evaluation Report.*

**Q#3 If the Turnpike Mainline Bridge over Abandoned Railroad at MP 56.3 is to be removed, what will replace it?**

*A#3 The existing bridge will be removed and replaced with embankment and a new widened roadway.*

**Q#4 Will geotechnical investigation be required?**

*A#4 Geotechnical services will be required to evaluate the subsurface conditions relative to the design and construction of embankments as part of the Phase I – Site Inspection and Engineering Investigation.*

**Q#5 What type of Protective Coating System evaluation (lead/asbestos) will be required for the superstructure of MP 56.1 and MP 58.5. Is this to be determined in the Scope of work meeting?**

*A#5 Evaluation of deficiencies of the existing PCS and the asbestos survey will be conducted during the Phase I – Site Inspection and Engineering Investigations.*

**Q#6 Are bridge inspection reports available for review?**

*A#6 The 2022 OTIC Bridge Inspection Report for each bridge is provided as part of this Addendum.*

**END OF ADDENDUM NO. 1**

# Ohio Bridge Inspection Summary Report

**LUC-0080K-0763R (4829492)**

2: District 74123 - SPRINGFIELD TWP (LUC county)  
ict  
02

5A: Inventory Route 1 0080K

21: Major Maint A/B 31 - State Toll Authority /  
225 Routine Main A/B 31 - State Toll Authority /  
221 Inspection A/B 31 - State Toll Authority /  
220: Inv. Location OHIO TURNPIKE

7: Facility On I80 OH TPK EB  
6: Feature Ints ALBON RD  
9: Location 3.5MI WEST OF EXIT 59  
Lat, Lon 41.5906238334074 , -83.737712393118

Condition		Structure Type	
<b>58: Deck</b>	<b>7 - Good Condition</b>	43: Bridge Type	4 - Steel continuous
58.01 Wearing Surface	7 - Good (1% distress)		02 - Stringer/Multi-beam or Girder
58.02 Joint	4 - Poor (heavy leaking, offset)		N - Not Applicable
<b>59: Superstructure</b>	<b>7 - Good Condition</b>	45: Spans Main / Approach	3 / 0
59.01 Paint & PCS	8 - Very Good (up to 1% corr.)	107: Deck Type	1 - Concrete Cast-in-Place
<b>60: Substructure</b>	<b>7 - Good Condition</b>	408: Composite Deck	N - Non-composite Construction
<b>61: Channel</b>	<b>N</b>	414A Joint Type 1	8 - Elastomeric Strip Seal
<b>61.01 Scour</b>	<b>N - Not Applicable</b>	414B: Joint Type 2	N - None
<b>62: Culverts</b>	<b>N - Not Applicable</b>	108A: Wearing Surface	1 - Monolithic Concrete (concurrently placed with structural deck)

**67.01 GA** 7

Appraisal		422: WS Date	
Sufficiency Rating	90.8 SD/FO 0 - ND	423: WS Thick (in)	1.0
36: Rail, Tr, Gd, Term Std	1 1 1 1	482: Protective Coating	1 - Red Lead
72: Approach Alignment	8 - Equal to present desirable criteria	483: PCS Date	01/01/1988
113: Scour Critical	N - Not over waterway	453: Bearing Type 1	A - Sliding (Other)
71: Waterway Adequacy	N - Not Applicable	455: Bearing Type 2	N - None
Geometric		528: Foundn: Abut Fwd	1 - Steel H Piles (Other size)
48: Max Span Length (ft)	58.0	533: Foundn: Abut Rear	1 - Steel H Piles (Other Size)
49: Structure Length (ft)	125.0	536: Foundn: Pier 1	1 - Steel H Piles (Other size)
52: Deck Width, Out-To-Out (ft)	40.3	539: Foundn: Pier 2	N - None (Such as most Culverts)
424: Deck Area (sf)	5037.5		
32: Appr Roadway Width (ft)	44.0		
51: Road Width, Curb-Curb (ft)	37.3		
50A: Curb/SW Width: Left (ft)	0		
50A: Curb/SW Width: Right (ft)	0		
34: Skew (deg)	8		
33: Bridge Median	0 - No median		
54B: Min Vert Underclearance (ft)	14.75		
336A: Min Vert Clrnce IR Cardinal (ft)	99		
336B: Min V Clr IR Non-Cardinal (ft)	0		
578: Culvert Length (ft)	0		

Age and Service	
27: Year Built/ 106 Rehab	1954 / 1987
42A: Service On	1 - Highway
42B: Service Under	1 - Highway, with or w/out pedestrian
28A: Lanes on	02
28B: Lanes Under	02
19: Bypass Length	1
29: ADT	12212
109: % Trucks (%)	43

Load Posting		Inspections	
41: Op/Post/Closed	A - Open	90: Routine Insp.	Months 24 05/18/2022
70: Posting	5 - Equal to or above legal loads	92A: FCM Insp.	N 0
70.01: Date		92B: Dive Insp.	N 0
70.02: Sign Type		92C: Special Insp.	N 0
734: Percent Legal (%)	150	92D: UBIT Insp.	N 0
704: Analysis Date	08/18/2017	92E: Drone Insp.	N 0
63: Analysis Method	6 - Load Factor (LF) rating reported by rating factor (RF) method using MS18 loading.	Inspector	Hayes, Edmund

Inspector: Edmund Hayes  
 Inspection Date: 05/18/2022

Structure Number: 4829492  
 Facility Carried: 180 OH TPK EB

### Bridge Inspection Report

### Element Inspection

	Environment	Total Quantity	Units	Condition State 1	Condition State 2	Condition State 3	Condition State 4
<b>12 - Reinforced Concrete Deck</b>	3 - Mod.	5038	sq. ft.	3375	1663	0	0
1130 - Cracking (RC and Other)		1663		0	1663	0	0
805 - Wearing Surface - Monolithic Concrete		4657	sq. ft.	2322	2327	7	1
<b>107 - Steel Open Girder/Beam</b>	3 - Mod.	750	ft.	750	0	0	0
515 - Steel Protective Coating		750	sq. ft.	732	18	0	0
Inspected prior to Paint SF Calculations, Quantified using Lineal Feet							

3440 - Effectiveness (Steel Protective Coatings)		18		0	18	0	0
<b>205 - Reinforced Concrete Column</b>	3 - Mod.	8	each	8	0	0	0
<b>215 - Reinforced Concrete Abutment</b>	3 - Mod.	82	ft.	51	20	11	0
1080 - Delamination/Spall/Patched Area		3		0	0	3	0
1120 - Efflorescence/Rust Staining		0		0	0	0	0
1130 - Cracking (RC and Other)		28		0	20	8	0
<b>234 - Reinforced Concrete Pier Cap</b>	3 - Mod.	82	ft.	21	61	0	0
1130 - Cracking (RC and Other)		61		0	61	0	0
<b>300 - Strip Seal Expansion Joint</b>	3 - Mod.	80	ft.	0	29	46	5
2310 - Leakage		60		0	10	46	4
2350 - Debris Impaction		8		0	8	0	0
2370 - Metal Deterioration or Damage		12		0	11	0	1
<b>311 - Movable Bearing</b>	3 - Mod.	24	each	12	0	7	5
1000 - Corrosion		7		0	0	7	0
2240 - Loss Bearing Area		5		0	0	0	5
515 - Steel Protective Coating		24	sq. ft.	12	0	12	0
3440 - Effectiveness (Steel Protective Coatings)		12		0	0	12	0
<b>321 - Reinforced Concrete Approach Slab</b>	3 - Mod.	1320	sq. ft.	816	500	4	0
1080 - Delamination/Spall/Patched Area		4		0	0	4	0
1190 - Abrasion/Wear (PSC/RC)		500		0	500	0	0
<b>331 - Reinforced Concrete Bridge Railing</b>	3 - Mod.	250	ft.	0	189	61	0
1080 - Delamination/Spall/Patched Area		10		0	0	10	0
1120 - Efflorescence/Rust Staining		0		0	0	0	0
1130 - Cracking (RC and Other)		101		0	50	51	0
1190 - Abrasion/Wear (PSC/RC)		139		0	139	0	0
<b>830 - Abutment Backwall</b>	3 - Mod.	82	ft.	50	31	1	0

ODOT District: District 02

## **LUC-0080K-0763R\_(4829492)**

Major Maint: 31 - State Toll Authority

Facility Carried: I80 OH TPK EB

Traffic On: 1 - Highway

Date Built: 07/01/1954

Rehab Date: 01/01/1987

Routine Maint: 31 - State Toll Authority

Feature Inters: ALBON RD

Traffic Under: 1 - Highway, with or w/out pedestrian

Insp. 31 - State Toll Authority

Resp A:

FIPS Code: 74123 - SPRINGFIELD TWP (LUC county)

Location: OHIO TURNPIKE

3.5MI WEST OF EXIT 59

Insp

Resp B:

Inspector

Hayes,Edmund

Inspection Date 05/18/2022

Reviewer Hayes,Edmund

### **Inspector Comments - Deck and Approach**

#### **Deck**

Deck is rated a 7 due to the prevalence of map cracking on the underside.

#### **Approach**

### **Inspector Comments - General Appraisal**

#### **Superstructure**

Superstructure is rated a 7 due to bearing issues such as uplift and deflections under liver load.

#### **Substructure**

Substructure is rated a 7 to cracks on most elements.

#### **Culvert**

### **Inspector Comments - Waterway**

#### **Waterway Adequacy**

#### **Channel**

#### **Scour Critical**

# Ohio Bridge Inspection Summary Report

**LUC-0080K-0763L (4829506)**

2: District 74123 - SPRINGFIELD TWP (LUC county)  
ict  
02

5A: Inventory Route 1 0080K

21: Major Maint A/B 31 - State Toll Authority /  
225 Routine Main A/B 31 - State Toll Authority /  
221 Inspection A/B 31 - State Toll Authority /  
220: Inv. Location OHIO TURNPIKE

7: Facility On I80 OH TPK WB  
6: Feature Ints ALBON RD  
9: Location 3.5MI WEST OF EXIT 59  
Lat, Lon 41.5908475067219 , -83.7377083698044

Condition		Structure Type	
<b>58: Deck</b>	<b>7 - Good Condition</b>	43: Bridge Type	4 - Steel continuous
58.01 Wearing Surface	7 - Good (1% distress)		02 - Stringer/Multi-beam or Girder
58.02 Joint	4- Poor (heavy leaking, offset)		N- Not Applicable
<b>59: Superstructure</b>	<b>7 - Good Condition</b>	45: Spans Main / Approach	3 / 0
59.01 Paint & PCS	8 - Very Good (up to 1% corr.)	107: Deck Type	1 - Concrete Cast-in-Place
<b>60: Substructure</b>	<b>7 - Good Condition</b>	408: Composite Deck	N - Non-composite Construction
<b>61: Channel</b>	<b>N</b>	414A Joint Type 1	8 - Elastomeric Strip Seal
61.01 Scour	<b>N - Not Applicable</b>	414B: Joint Type 2	N - None
<b>62: Culverts</b>	<b>N - Not Applicable</b>	108A: Wearing Surface	1 - Monolithic Concrete (concurrently placed with structural deck) N- Not Applicable

**67.01 GA 7**

Appraisal	
Sufficiency Rating	89.8 SD/FO 0 - ND
36: Rail, Tr, Gd, Term Std	1 1 1 1
72: Approach Alignment	8 - Equal to present desirable criteria
113: Scour Critical	N - Not over waterway
71: Waterway Adequacy	N - Not Applicable

Geometric	
48: Max Span Length (ft)	58.0
49: Structure Length (ft)	125.0
52: Deck Width, Out-To-Out (ft)	40.3
424: Deck Area (sf)	5037.5
32: Appr Roadway Width (ft)	44.0
51: Road Width, Curb-Curb (ft)	37.3
50A: Curb/SW Width: Left (ft)	0
50A: Curb/SW Width: Right (ft)	0
34: Skew (deg)	8
33: Bridge Median	0 - No median
54B: Min Vert Underclearance (ft)	14.25
336A: Min Vert Clrnce IR Cardinal (ft)	99
336B: Min V Clr IR Non-Cardinal (ft)	0
578: Culvert Length (ft)	0

Load Posting	
41: Op/Post/Closed	A - Open
70: Posting	5 - Equal to or above legal loads
70.01: Date	
70.02: Sign Type	
734: Percent Legal (%)	150
704: Analysis Date	08/18/2017
63: Analysis Method	6 - Load Factor (LF) rating reported by rating factor (RF) method using MS18 loading.

422: WS Date	
423: WS Thick (in)	1.0
482: Protective Coating	1 - Red Lead
483: PCS Date	01/01/1988
453: Bearing Type 1	A - Sliding (Other)
455: Bearing Type 2	N - None
528: Foundn: Abut Fwd	1 - Steel H Piles (Other size)
533: Foundn: Abut Rear	1 - Steel H Piles (Other Size)
536: Foundn: Pier 1	1 - Steel H Piles (Other size)
539: Foundn: Pier 2	N - None (Such as most Culverts)

Age and Service	
27: Year Built/ 106 Rehab	1954 / 1987
42A: Service On	1 - Highway
42B: Service Under	1 - Highway, with or w/out pedestrian
28A: Lanes on	02
28B: Lanes Under	02
19: Bypass Length	1
29: ADT	12212
109: % Trucks (%)	43

Inspections	
90: Routine Insp.	Months 24 05/17/2022
92A: FCM Insp.	N 0
92B: Dive Insp.	N 0
92C: Special Insp.	N 0
92D: UBIT Insp.	N 0
92E: Drone Insp.	N 0
Inspector	Hayes, Edmund

Inspector: Edmund Hayes  
 Inspection Date: 05/17/2022

Structure Number: 4829506  
 Facility Carried: I80 OH TPK WB

### Bridge Inspection Report

### Element Inspection

	Environment	Total Quantity	Units	Condition State 1	Condition State 2	Condition State 3	Condition State 4
12 - Reinforced Concrete Deck	3 - Mod.	5038	sq. ft.	3375	1663	0	0
1130 - Cracking (RC and Other)		1663		0	1663	0	0
805 - Wearing Surface - Monolithic Concrete		4657	sq. ft.	3489	1164	4	0
107 - Steel Open Girder/Beam	3 - Mod.	750	ft.	712	38	0	0
1900 - Distortion		38		0	38	0	0
515 - Steel Protective Coating		750	sq. ft.	732	18	0	0
Inspected prior to Paint SF Calculations, Quantified using Lineal Feet							

3440 - Effectiveness (Steel Protective Coatings)		18		0	18	0	0
205 - Reinforced Concrete Column	3 - Mod.	8	each	8	0	0	0
215 - Reinforced Concrete Abutment	3 - Mod.	82	ft.	55	25	2	0
1120 - Efflorescence/Rust Staining		2		0	0	2	0
1130 - Cracking (RC and Other)		25		0	25	0	0
234 - Reinforced Concrete Pier Cap	3 - Mod.	82	ft.	32	50	0	0
1130 - Cracking (RC and Other)		50		0	50	0	0
300 - Strip Seal Expansion Joint	3 - Mod.	88	ft.	0	67	21	0
2310 - Leakage		41		0	20	21	0
2350 - Debris Impaction		23		0	23	0	0
2370 - Metal Deterioration or Damage		24		0	24	0	0
311 - Movable Bearing	3 - Mod.	24	each	16	3	2	3
1000 - Corrosion		4		0	3	1	0
2240 - Loss Bearing Area		4		0	0	1	3
515 - Steel Protective Coating		24	sq. ft.	12	0	11	1
3440 - Effectiveness (Steel Protective Coatings)		12		0	0	11	1
321 - Reinforced Concrete Approach Slab	3 - Mod.	1320	sq. ft.	808	511	1	0
1080 - Delamination/Spall/Patched Area		2		0	1	1	0
1130 - Cracking (RC and Other)		10		0	10	0	0
1190 - Abrasion/Wear (PSC/RC)		500		0	500	0	0
331 - Reinforced Concrete Bridge Railing	3 - Mod.	250	ft.	234	16	0	0
1080 - Delamination/Spall/Patched Area		6		0	6	0	0
1130 - Cracking (RC and Other)		0		0	0	0	0
1190 - Abrasion/Wear (PSC/RC)		10		0	10	0	0
830 - Abutment Backwall	3 - Mod.	82	ft.	69	13	0	0

ODOT District: District 02

## **LUC-0080K-0763L\_(4829506)**

Major Maint: 31 - State Toll Authority

Facility Carried: I80 OH TPK WB

Traffic On: 1 - Highway

Date Built: 07/01/1954

Rehab Date: 01/01/1987

Routine Maint: 31 - State Toll Authority

Feature Inters: ALBON RD

Traffic Under: 1 - Highway, with or w/out pedestrian

Insp. 31 - State Toll Authority

FIPS Code: 74123 - SPRINGFIELD TWP (LUC county)

Location: OHIO TURNPIKE

3.5MI WEST OF EXIT 59

Resp A:

Insp

Resp B:

Inspector

Hayes,Edmund

Inspection Date 05/17/2022

Reviewer Hayes,Edmund

### **Inspector Comments - Deck and Approach**

#### **Deck**

Deck is rated a 7 due to the prevalence of map cracking on the underside.

#### **Approach**

### **Inspector Comments - General Appraisal**

#### **Superstructure**

Superstructure is rated a 7 due to bearing issues such as deflections under live load.

#### **Substructure**

Substructure is rated a 7 for cracking on most elements.

#### **Culvert**

### **Inspector Comments - Waterway**

#### **Waterway Adequacy**

#### **Channel**

#### **Scour Critical**



# Ohio Bridge Inspection Summary Report

**LUC-0080K-0788R (4829522)**

2: District 74123 - SPRINGFIELD TWP (LUC county)  
ict  
02

5A: Inventory Route 1 0080K

21: Major Maint A/B 31 - State Toll Authority /  
225 Routine Main A/B 31 - State Toll Authority /  
221 Inspection A/B 31 - State Toll Authority /  
220: Inv. Location OHIO TURNPIKE

7: Facility On I80 OH TPK EB  
6: Feature Ints CONRAIL RR (ABD)  
9: Location 3.3MI WEST OF EXIT 59  
Lat, Lon 41.5911418200506 , -83.7328691139844

Condition		Structure Type	
<b>58: Deck</b>	<b>8 - Very Good Condition</b>	43: Bridge Type	4 - Steel continuous
58.01 Wearing Surface	7 - Good (1% distress)		02 - Stringer/Multi-beam or Girder
58.02 Joint	7- Good (no leaking)		N- Not Applicable
<b>59: Superstructure</b>	<b>6 - Satisfactory Condition</b>	45: Spans Main / Approach	3 / 0
59.01 Paint & PCS	3 - Serious PCS (20-30% corr.)	107: Deck Type	1 - Concrete Cast-in-Place
<b>60: Substructure</b>	<b>6 - Satisfactory Condition</b>	408: Composite Deck	N - Non-composite Construction
<b>61: Channel</b>	<b>N</b>	414A Joint Type 1	8 - Elastomeric Strip Seal
61.01 Scour	<b>N - Not Applicable</b>	414B: Joint Type 2	N - None
<b>62: Culverts</b>	<b>N - Not Applicable</b>	108A: Wearing Surface	1 - Monolithic Concrete (concurrently placed with structural deck)

**67.01 GA** 6

Appraisal	
Sufficiency Rating	89.8 SD/FO 0 - ND
36: Rail, Tr, Gd, Term Std	1 1 1 1
72: Approach Alignment	8 - Equal to present desirable criteria
113: Scour Critical	N - Not over waterway
71: Waterway Adequacy	N - Not Applicable

Geometric	
48: Max Span Length (ft)	33.0
49: Structure Length (ft)	98.0
52: Deck Width, Out-To-Out (ft)	40.3
424: Deck Area (sf)	3949.4
32: Appr Roadway Width (ft)	44.0
51: Road Width, Curb-Curb (ft)	37.3
50A: Curb/SW Width: Left (ft)	0
50A: Curb/SW Width: Right (ft)	0
34: Skew (deg)	8
33: Bridge Median	0 - No median
54B: Min Vert Underclearance (ft)	23.08
336A: Min Vert Clrnce IR Cardinal (ft)	99
336B: Min V Clr IR Non-Cardinal (ft)	0
578: Culvert Length (ft)	0

Load Posting	
41: Op/Post/Closed	A - Open
70: Posting	5 - Equal to or above legal loads
70.01: Date	
70.02: Sign Type	
734: Percent Legal (%)	150
704: Analysis Date	08/08/2017
63: Analysis Method	6 - Load Factor (LF) rating reported by rating factor (RF) method using MS18 loading.

422: WS Date	
423: WS Thick (in)	1.0
482: Protective Coating	1 - Red Lead
483: PCS Date	01/01/1988
453: Bearing Type 1	A - Sliding (Other)
455: Bearing Type 2	N - None
528: Foundn: Abut Fwd	2 - Cast-in-Place Reinforced Concrete Piles (Other diameter)
533: Foundn: Abut Rear	2 - Cast-in-Place reinforced Concrete Piles (Other diameter)
536: Foundn: Pier 1	2 - Cast-in-Place Reinforced Concrete Piles (Other diameter)
539: Foundn: Pier 2	N - None (Such as most Culverts)

Age and Service	
27: Year Built/ 106 Rehab	1954 / 1987
42A: Service On	1 - Highway
42B: Service Under	2 - Railroad
28A: Lanes on	02
28B: Lanes Under	00
19: Bypass Length	1
29: ADT	12212
109: % Trucks (%)	43

Inspections	
90: Routine Insp.	Months 12 05/17/2022
92A: FCM Insp.	N 0
92B: Dive Insp.	N 0
92C: Special Insp.	N 0
92D: UBIT Insp.	N 0
92E: Drone Insp.	N 0
Inspector	Hayes, Edmund

Inspector: Edmund Hayes  
 Inspection Date: 05/17/2022

Structure Number: 4829522  
 Facility Carried: I80 OH TPK EB

### Bridge Inspection Report

### Element Inspection

	Environment	Total Quantity	Units	Condition State 1	Condition State 2	Condition State 3	Condition State 4
12 - Reinforced Concrete Deck	3 - Mod.	3950	sq. ft.	3752	198	0	0
1130 - Cracking (RC and Other)		198		0	198	0	0
805 - Wearing Surface - Monolithic Concrete		3651	sq. ft.	2738	913	0	0
107 - Steel Open Girder/Beam	3 - Mod.	588	ft.	402	186	0	0
1000 - Corrosion		186		0	186	0	0
515 - Steel Protective Coating		588	sq. ft.	0	177	30	381
Inspected prior to Paint SF Calculations, Quantified using Lineal Feet							

3440 - Effectiveness (Steel Protective Coatings)		588		0	177	30	381
205 - Reinforced Concrete Column	3 - Mod.	8	each	6	2	0	0
1130 - Cracking (RC and Other)		2		0	2	0	0
215 - Reinforced Concrete Abutment	3 - Mod.	82	ft.	44	34	4	0
1080 - Delamination/Spall/Patched Area		2		0	0	2	0
1130 - Cracking (RC and Other)		36		0	34	2	0
234 - Reinforced Concrete Pier Cap	3 - Mod.	82	ft.	18	64	0	0
1080 - Delamination/Spall/Patched Area		3		0	3	0	0
1130 - Cracking (RC and Other)		61		0	61	0	0
300 - Strip Seal Expansion Joint	3 - Mod.	80	ft.	48	32	0	0
2370 - Metal Deterioration or Damage		32		0	32	0	0
311 - Movable Bearing	3 - Mod.	24	each	9	10	1	4
2210 - Movement		9		0	9	0	0
2240 - Loss Bearing Area		6		0	1	1	4
515 - Steel Protective Coating		24	sq. ft.	0	12	8	4
3440 - Effectiveness (Steel Protective Coatings)		24		0	12	8	4
321 - Reinforced Concrete Approach Slab	3 - Mod.	746	sq. ft.	543	201	2	0
1080 - Delamination/Spall/Patched Area		16		0	14	2	0
1190 - Abrasion/Wear (PSC/RC)		187		0	187	0	0
331 - Reinforced Concrete Bridge Railing	3 - Mod.	196	ft.	0	109	85	2
1080 - Delamination/Spall/Patched Area		18		0	0	16	2
1130 - Cracking (RC and Other)		49		0	0	49	0
1190 - Abrasion/Wear (PSC/RC)		129		0	109	20	0
830 - Abutment Backwall	3 - Mod.	82	ft.	71	11	0	0

ODOT District: District 02

## **LUC-0080K-0788R\_(4829522)**

Major Maint: 31 - State Toll Authority

Facility Carried: I80 OH TPK EB

Traffic On: 1 - Highway

Date Built: 07/01/1954

Rehab Date: 01/01/1987

Routine Maint: 31 - State Toll Authority

Feature Inters: CONRAIL RR (ABD)

Traffic Under: 2 - Railroad

Insp. 31 - State Toll Authority

FIPS Code: 74123 - SPRINGFIELD TWP (LUC county)

Location: OHIO TURNPIKE

3.3MI WEST OF EXIT 59

Resp A:

Insp

Resp B:

Inspector

Hayes,Edmund

Inspection Date 05/17/2022

Reviewer Hayes,Edmund

### **Inspector Comments - Deck and Approach**

#### **Deck**

Deck is raised to an 8, inspection found only minimal cracking not exceeding 10%.

#### **Approach**

### **Inspector Comments - General Appraisal**

#### **Superstructure**

Superstructure is rated a 6 for surface corrosion on fascia girders, with spot surface corrosion developing on exposed bare steel. There are also significant bearing issues.

#### **Substructure**

Substructure was lowered to a 6 as 2 abutment spalls are affecting bearing area.

#### **Culvert**

### **Inspector Comments - Waterway**

#### **Waterway Adequacy**

#### **Channel**

#### **Scour Critical**

# Ohio Bridge Inspection Summary Report

LUC-0080K-0788L (4829530)

2: District 74123 - SPRINGFIELD TWP (LUC county)  
ict  
02

5A: Inventory Route 1 0080K

21: Major Maint A/B 31 - State Toll Authority /  
225 Routine Main A/B 31 - State Toll Authority /  
221 Inspection A/B 31 - State Toll Authority /  
220: Inv. Location OHIO TURNPIKE

7: Facility On I80 OH TPK WB  
6: Feature Ints CONRAIL RR (ABD)  
9: Location 3.3MI WEST OF EXIT 59  
Lat, Lon 41.5913654915703 , -83.7328691139844

Condition		Structure Type	
58: Deck	8 - Very Good Condition	43: Bridge Type	4 - Steel continuous
58.01 Wearing Surface	7 - Good (1% distress)		02 - Stringer/Multi-beam or Girder
58.02 Joint	6- Satisfactory (isolated leaking)		N- Not Applicable
59: Superstructure	6 - Satisfactory Condition	45: Spans Main / Approach	3 / 0
59.01 Paint & PCS	2 - Critical PCS (30-40% corr.)	107: Deck Type	1 - Concrete Cast-in-Place
60: Substructure	7 - Good Condition	408: Composite Deck	N - Non-composite Construction
61: Channel	N	414A Joint Type 1	8 - Elastomeric Strip Seal
61.01 Scour	N - Not Applicable	414B: Joint Type 2	N - None
62: Culverts	N - Not Applicable	108A: Wearing Surface	1 - Monolithic Concrete (concurrently placed with structural deck)

67.01 GA 6

Appraisal	
Sufficiency Rating	89.8 SD/FO 0 - ND
36: Rail, Tr, Gd, Term Std	1 1 1 1
72: Approach Alignment	8 - Equal to present desirable criteria
113: Scour Critical	N - Not over waterway
71: Waterway Adequacy	N - Not Applicable

Geometric	
48: Max Span Length (ft)	33.0
49: Structure Length (ft)	98.0
52: Deck Width, Out-To-Out (ft)	40.3
424: Deck Area (sf)	3949.4
32: Appr Roadway Width (ft)	44.0
51: Road Width, Curb-Curb (ft)	37.3
50A: Curb/SW Width: Left (ft)	0
50A: Curb/SW Width: Right (ft)	0
34: Skew (deg)	8
33: Bridge Median	0 - No median
54B: Min Vert Underclearance (ft)	32
336A: Min Vert Clrnce IR Cardinal (ft)	99
336B: Min V Clr IR Non-Cardinal (ft)	0
578: Culvert Length (ft)	0

Load Posting	
41: Op/Post/Closed	A - Open
70: Posting	5 - Equal to or above legal loads
70.01: Date	
70.02: Sign Type	
734: Percent Legal (%)	150
704: Analysis Date	08/08/2017
63: Analysis Method	6 - Load Factor (LF) rating reported by rating factor (RF) method using MS18 loading.

422: WS Date	
423: WS Thick (in)	1.0
482: Protective Coating	1 - Red Lead
483: PCS Date	01/01/1988
453: Bearing Type 1	A - Sliding (Other)
455: Bearing Type 2	N - None
528: Foundn: Abut Fwd	2 - Cast-in-Place Reinforced Concrete Piles (Other diameter)
533: Foundn: Abut Rear	2 - Cast-in-Place reinforced Concrete Piles (Other diameter)
536: Foundn: Pier 1	2 - Cast-in-Place Reinforced Concrete Piles (Other diameter)
539: Foundn: Pier 2	N - None (Such as most Culverts)

Age and Service	
27: Year Built/ 106 Rehab	1954 / 1987
42A: Service On	1 - Highway
42B: Service Under	2 - Railroad
28A: Lanes on	02
28B: Lanes Under	00
19: Bypass Length	1
29: ADT	12212
109: % Trucks (%)	43

Inspections	
90: Routine Insp.	Months 12 05/17/2022
92A: FCM Insp.	N 0
92B: Dive Insp.	N 0
92C: Special Insp.	N 0
92D: UBIT Insp.	N 0
92E: Drone Insp.	N 0
Inspector	Hayes, Edmund

Inspector: Edmund Hayes  
 Inspection Date: 05/17/2022

Structure Number: 4829530  
 Facility Carried: I80 OH TPK WB

# Bridge Inspection Report

## Element Inspection

	Environment	Total Quantity	Units	Condition State 1	Condition State 2	Condition State 3	Condition State 4
12 - Reinforced Concrete Deck	3 - Mod.	3950	sq. ft.	3752	198	0	0
805 - Wearing Surface - Monolithic Concrete		3651	sq. ft.	2920	730	0	1
107 - Steel Open Girder/Beam	3 - Mod.	588	ft.	402	186	0	0
1000 - Corrosion		186		0	186	0	0
515 - Steel Protective Coating		588	sq. ft.	0	117	59	412
Inspected prior to Paint SF Calculations, Quantified using Lineal Feet							

3440 - Effectiveness (Steel Protective Coatings)		588		0	117	59	412
205 - Reinforced Concrete Column	3 - Mod.	8	each	4	4	0	0
1130 - Cracking (RC and Other)		4		0	4	0	0
215 - Reinforced Concrete Abutment	3 - Mod.	82	ft.	35	46	1	0
1120 - Efflorescence/Rust Staining		1		0	0	1	0
1130 - Cracking (RC and Other)		46		0	46	0	0
234 - Reinforced Concrete Pier Cap	3 - Mod.	82	ft.	29	40	13	0
1130 - Cracking (RC and Other)		53		0	40	13	0
300 - Strip Seal Expansion Joint	3 - Mod.	80	ft.	43	32	5	0
2370 - Metal Deterioration or Damage		37		0	32	5	0
311 - Movable Bearing	3 - Mod.	24	each	12	2	5	5
1000 - Corrosion		4		0	2	2	0
2240 - Loss Bearing Area		8		0	0	3	5
515 - Steel Protective Coating		24	sq. ft.	0	12	8	4
321 - Reinforced Concrete Approach Slab	3 - Mod.	746	sq. ft.	548	197	1	0
1080 - Delamination/Spall/Patched Area		2		0	1	1	0
1130 - Cracking (RC and Other)		10		0	10	0	0
1190 - Abrasion/Wear (PSC/RC)		186		0	186	0	0
331 - Reinforced Concrete Bridge Railing	3 - Mod.	196	ft.	125	70	1	0
1080 - Delamination/Spall/Patched Area		31		0	30	1	0
1130 - Cracking (RC and Other)		10		0	10	0	0
1190 - Abrasion/Wear (PSC/RC)		30		0	30	0	0
830 - Abutment Backwall	3 - Mod.	82	ft.	56	26	0	0

ODOT District: District 02

**LUC-0080K-0788L\_(4829530)**

Major Maint: 31 - State Toll Authority

Facility Carried: I80 OH TPK WB

Traffic On: 1 - Highway

Date Built: 07/01/1954

Rehab Date: 01/01/1987

Routine Maint: 31 - State Toll Authority

Feature Inters: CONRAIL RR (ABD)

Traffic Under: 2 - Railroad

Insp. 31 - State Toll Authority

FIPS Code: 74123 - SPRINGFIELD TWP (LUC county)

Location: OHIO TURNPIKE

3.3MI WEST OF EXIT 59

Resp A:

Insp

Resp B:

Inspector

Hayes,Edmund

Inspection Date 05/17/2022

Reviewer Hayes,Edmund

## **Inspector Comments - Deck and Approach**

### **Deck**

Deck is raised to an 8 as only a small amount of cracking not exceeding 10% is present.

### **Approach**

## **Inspector Comments - General Appraisal**

### **Superstructure**

Superstructure is rated a 6 for surface corrosion on fascia girders, with spot surface corrosion developing on exposed bare steel. There are also significant bearing issues.

### **Substructure**

Substructure is rated a 7 due to cracking on all elements.

### **Culvert**

## **Inspector Comments - Waterway**

### **Waterway Adequacy**

### **Channel**

### **Scour Critical**

# Ohio Bridge Inspection Summary Report

**LUC-0080K-1010R (4829603)**

2: District 74123 - SPRINGFIELD TWP (LUC county)  
ict  
02

5A: Inventory Route 1 0080K

21: Major Maint A/B 31 - State Toll Authority /  
225 Routine Main A/B 31 - State Toll Authority /  
221 Inspection A/B 31 - State Toll Authority /  
220: Inv. Location OHIO TURNPIKE

7: Facility On I80 OH TPK EB  
6: Feature Ints SWAN CREEK  
9: Location 1.1MI WEST OF EXIT 59  
Lat, Lon 41.5918744 , -83.6902407

Condition		Structure Type	
58: Deck	8 - Very Good Condition	43: Bridge Type	4 - Steel continuous
58.01 Wearing Surface	7 - Good (1% distress)		02 - Stringer/Multi-beam or Girder
58.02 Joint	7- Good (no leaking)		N- Not Applicable
59: Superstructure	7 - Good Condition	45: Spans Main / Approach	3 / 0
59.01 Paint & PCS	5 - Fair (10-15% corr.)	107: Deck Type	1 - Concrete Cast-in-Place
60: Substructure	7 - Good Condition	408: Composite Deck	N - Non-composite Construction
61: Channel	7	414A Joint Type 1	8 - Elastomeric Strip Seal
61.01 Scour	6 - Satisfactory	414B: Joint Type 2	N - None
62: Culverts	N - Not Applicable	108A: Wearing Surface	1 - Monolithic Concrete (concurrently placed with structural deck)
			N- Not Applicable
67.01 GA	7		

Appraisal		422: WS Date	
Sufficiency Rating	90.8 SD/FO 0 - ND	423: WS Thick (in)	1.2
36: Rail, Tr, Gd, Term Std	1 1 1 1	482: Protective Coating	1 - Red Lead
72: Approach Alignment	8 - Equal to present desirable criteria	483: PCS Date	01/01/1983
113: Scour Critical	8 - Stable for scour conditions	453: Bearing Type 1	A - Sliding (Other)
71: Waterway Adequacy	8 - Bridge Above Approaches	455: Bearing Type 2	N - None

Geometric		528: Foundn: Abut Fwd	1 - Steel H Piles (Other size)
48: Max Span Length (ft)	55.0	533: Foundn: Abut Rear	1 - Steel H Piles (Other Size)
49: Structure Length (ft)	148.0	536: Foundn: Pier 1	1 - Steel H Piles (Other size)
52: Deck Width, Out-To-Out (ft)	40.3	539: Foundn: Pier 2	N - None (Such as most Culverts)
424: Deck Area (sf)	5964.4		
32: Appr Roadway Width (ft)	44.0		
51: Road Width, Curb-Curb (ft)	37.3		
50A: Curb/SW Width: Left (ft)	0		
50A: Curb/SW Width: Right (ft)	0		
34: Skew (deg)	30		
33: Bridge Median	0 - No median		
54B: Min Vert Underclearance (ft)	0		
336A: Min Vert Clrnce IR Cardinal (ft)	99		
336B: Min V Clr IR Non-Cardinal (ft)	0		
578: Culvert Length (ft)	0		

Age and Service		27: Year Built/ 106 Rehab	1954 / 1987
42A: Service On	1 - Highway		
42B: Service Under	5 - Waterway		
28A: Lanes on	02		
28B: Lanes Under	00		
19: Bypass Length	1		
29: ADT	12212		
109: % Trucks (%)	43		

Load Posting		Inspections	
41: Op/Post/Closed	A - Open	90: Routine Insp.	Months 24 05/24/2022
70: Posting	5 - Equal to or above legal loads	92A: FCM Insp.	N 0
70.01: Date		92B: Dive Insp.	N 0
70.02: Sign Type		92C: Special Insp.	N 0
734: Percent Legal (%)	150	92D: UBIT Insp.	N 0
704: Analysis Date	08/29/2017	92E: Drone Insp.	N 0
63: Analysis Method	6 - Load Factor (LF) rating reported by rating factor (RF) method using MS18 loading.	Inspector	Nelson, Tanner

Inspector: Tanner Nelson  
 Inspection Date: 05/24/2022

Structure Number: 4829603  
 Facility Carried: I80 OH TPK EB

### Bridge Inspection Report

### Element Inspection

	Environment	Total Quantity	Units	Condition State 1	Condition State 2	Condition State 3	Condition State 4
12 - Reinforced Concrete Deck	3 - Mod.	5957	sq. ft.	5629	328	0	0
1130 - Cracking (RC and Other)		328		0	328	0	0
805 - Wearing Surface - Monolithic Concrete		5526	sq. ft.	5470	56	0	0
107 - Steel Open Girder/Beam	3 - Mod.	888	ft.	730	148	10	0
1000 - Corrosion		158		0	148	10	0
515 - Steel Protective Coating		888	sq. ft.	0	444	133	311
Inspected prior to Paint SF Calculations, Quantified using Lineal Feet							

3440 - Effectiveness (Steel Protective Coatings)		888		0	444	133	311
205 - Reinforced Concrete Column	3 - Mod.	8	each	8	0	0	0
215 - Reinforced Concrete Abutment	3 - Mod.	93	ft.	75	18	0	0
1080 - Delamination/Spall/Patched Area		4		0	4	0	0
1130 - Cracking (RC and Other)		14		0	14	0	0
234 - Reinforced Concrete Pier Cap	3 - Mod.	93	ft.	43	50	0	0
1130 - Cracking (RC and Other)		50		0	50	0	0
300 - Strip Seal Expansion Joint	3 - Mod.	80	ft.	70	10	0	0
2360 - Adjacent Deck or Header		10		0	10	0	0
311 - Movable Bearing	3 - Mod.	24	each	8	6	9	1
1000 - Corrosion		15		0	6	9	0
2240 - Loss Bearing Area		1		0	0	0	1
321 - Reinforced Concrete Approach Slab	3 - Mod.	1320	sq. ft.	1255	65	0	0
1080 - Delamination/Spall/Patched Area		25		0	25	0	0
1130 - Cracking (RC and Other)		40		0	40	0	0
331 - Reinforced Concrete Bridge Railing	3 - Mod.	296	ft.	249	44	3	0
1080 - Delamination/Spall/Patched Area		3		0	0	3	0
1130 - Cracking (RC and Other)		44		0	44	0	0
830 - Abutment Backwall	3 - Mod.	93	ft.	88	5	0	0



ODOT District: District 02

## **LUC-0080K-1010R\_(4829603)**

Major Maint: 31 - State Toll Authority

Facility Carried: I80 OH TPK EB

Traffic On: 1 - Highway

Date Built: 07/01/1954

Rehab Date: 01/01/1987

Routine Maint: 31 - State Toll Authority

Feature Inters: SWAN CREEK

Traffic Under: 5 - Waterway

Insp. 31 - State Toll Authority

FIPS Code: 74123 - SPRINGFIELD TWP (LUC county)

Location: OHIO TURNPIKE

1.1MI WEST OF EXIT 59

Resp A:

Insp

Resp B:

Inspector

Nelson,Tanner

Inspection Date 05/24/2022

Reviewer Hayes,Edmund

### **Inspector Comments - Deck and Approach**

#### **Deck**

The deck was raised to an 8 due to only a minimal amount of racking on the underside not exceeding 10% by area.

#### **Approach**

### **Inspector Comments - General Appraisal**

#### **Superstructure**

The superstructure was rated a 7 due to areas of corrosion in the bottom flanges of the fascia girders. One bearing deflects as well.

#### **Substructure**

The substructure was rated a 7 due to cracking throughout pier caps and abutment walls.

#### **Culvert**

### **Inspector Comments - Waterway**

#### **Waterway Adequacy**

#### **Channel**

Channel is rated a 7 for minor debris in the channel.

#### **Scour Critical**

# Ohio Bridge Inspection Summary Report

LUC-0080K-1010L (4829611)

2: District 74123 - SPRINGFIELD TWP (LUC county)  
ict  
02

5A: Inventory Route 1 0080K

21: Major Maint A/B 31 - State Toll Authority /  
225 Routine Main A/B 31 - State Toll Authority /  
221 Inspection A/B 31 - State Toll Authority /  
220: Inv. Location OHIO TURNPIKE

7: Facility On I80 OH TPK WB  
6: Feature Ints SWAN CREEK  
9: Location 1.1MI WEST OF EXIT 59  
Lat, Lon 41.592092518329 , -83.6900404703667

Condition		Structure Type	
58: Deck	8 - Very Good Condition	43: Bridge Type	4 - Steel continuous
58.01 Wearing Surface	7 - Good (1% distress)		02 - Stringer/Multi-beam or Girder
58.02 Joint	7- Good (no leaking)		N- Not Applicable
59: Superstructure	7 - Good Condition	45: Spans Main / Approach	3 / 0
59.01 Paint & PCS	5 - Fair (10-15% corr.)	107: Deck Type	1 - Concrete Cast-in-Place
60: Substructure	7 - Good Condition	408: Composite Deck	N - Non-composite Construction
61: Channel	7	414A Joint Type 1	8 - Elastomeric Strip Seal
61.01 Scour	6 - Satisfactory	414B: Joint Type 2	N - None
62: Culverts	N - Not Applicable	108A: Wearing Surface	1 - Monolithic Concrete (concurrently placed with structural deck)
			N- Not Applicable
67.01 GA	7		

Appraisal	
Sufficiency Rating	90.8 SD/FO 0 - ND
36: Rail, Tr, Gd, Term Std	1 1 1 1
72: Approach Alignment	8 - Equal to present desirable criteria
113: Scour Critical	8 - Stable for scour conditions
71: Waterway Adequacy	8 - Bridge Above Approaches

Geometric	
48: Max Span Length (ft)	55.0
49: Structure Length (ft)	148.0
52: Deck Width, Out-To-Out (ft)	40.3
424: Deck Area (sf)	5964.4
32: Appr Roadway Width (ft)	44.0
51: Road Width, Curb-Curb (ft)	37.3
50A: Curb/SW Width: Left (ft)	0
50A: Curb/SW Width: Right (ft)	0
34: Skew (deg)	30
33: Bridge Median	0 - No median
54B: Min Vert Underclearance (ft)	0
336A: Min Vert Clrnce IR Cardinal (ft)	99
336B: Min V Clr IR Non-Cardinal (ft)	0
578: Culvert Length (ft)	0

Load Posting	
41: Op/Post/Closed	A - Open
70: Posting	5 - Equal to or above legal loads
70.01: Date	
70.02: Sign Type	
734: Percent Legal (%)	150
704: Analysis Date	08/29/2017
63: Analysis Method	6 - Load Factor (LF) rating reported by rating factor (RF) method using MS18 loading.

422: WS Date	
423: WS Thick (in)	1.2
482: Protective Coating	1 - Red Lead
483: PCS Date	01/01/1983
453: Bearing Type 1	A - Sliding (Other)
455: Bearing Type 2	N - None
528: Foundn: Abut Fwd	1 - Steel H Piles (Other size)
533: Foundn: Abut Rear	1 - Steel H Piles (Other Size)
536: Foundn: Pier 1	1 - Steel H Piles (Other size)
539: Foundn: Pier 2	N - None (Such as most Culverts)

Age and Service	
27: Year Built/ 106 Rehab	1954 / 1987
42A: Service On	1 - Highway
42B: Service Under	5 - Waterway
28A: Lanes on	02
28B: Lanes Under	00
19: Bypass Length	1
29: ADT	12212
109: % Trucks (%)	43

Inspections	
90: Routine Insp.	Months 24 05/24/2022
92A: FCM Insp.	N 0
92B: Dive Insp.	N 0
92C: Special Insp.	N 0
92D: UBIT Insp.	N 0
92E: Drone Insp.	N 0
Inspector	Nelson, Tanner

Inspector: Tanner Nelson  
 Inspection Date: 05/24/2022

Structure Number: 4829611  
 Facility Carried: I80 OH TPK WB

# Bridge Inspection Report

## Element Inspection

	Environment	Total Quantity	Units	Condition State 1	Condition State 2	Condition State 3	Condition State 4
12 - Reinforced Concrete Deck	3 - Mod.	5957	sq. ft.	5659	298	0	0
1130 - Cracking (RC and Other)		298		0	298	0	0
805 - Wearing Surface - Monolithic Concrete		5526	sq. ft.	5526	0	0	0
107 - Steel Open Girder/Beam	3 - Mod.	888	ft.	688	200	0	0
1000 - Corrosion		200		0	200	0	0
515 - Steel Protective Coating		888	sq. ft.	0	444	133	311
Inspected prior to Paint SF Calculations, Quantified using Lineal Feet							

3440 - Effectiveness (Steel Protective Coatings)		888		0	444	133	311
205 - Reinforced Concrete Column	3 - Mod.	8	each	8	0	0	0
215 - Reinforced Concrete Abutment	3 - Mod.	93	ft.	78	15	0	0
1130 - Cracking (RC and Other)		15		0	15	0	0
234 - Reinforced Concrete Pier Cap	3 - Mod.	93	ft.	28	65	0	0
1130 - Cracking (RC and Other)		65		0	65	0	0
300 - Strip Seal Expansion Joint	3 - Mod.	80	ft.	56	24	0	0
2370 - Metal Deterioration or Damage		24		0	24	0	0
311 - Movable Bearing	3 - Mod.	24	each	6	6	11	1
1000 - Corrosion		5		0	0	5	0
1020 - Connection		6		0	6	0	0
2240 - Loss Bearing Area		7		0	0	6	1
321 - Reinforced Concrete Approach Slab	3 - Mod.	2200	sq. ft.	2090	110	0	0
331 - Reinforced Concrete Bridge Railing	3 - Mod.	296	ft.	281	15	0	0
1130 - Cracking (RC and Other)		15		0	15	0	0
830 - Abutment Backwall	3 - Mod.	93	ft.	88	5	0	0

ODOT District: District 02

## **LUC-0080K-1010L\_(4829611)**

Major Maint: 31 - State Toll Authority

Facility Carried: I80 OH TPK WB

Traffic On: 1 - Highway

Date Built: 07/01/1954

Rehab Date: 01/01/1987

Routine Maint: 31 - State Toll Authority

Feature Inters: SWAN CREEK

Traffic Under: 5 - Waterway

Insp. 31 - State Toll Authority

FIPS Code: 74123 - SPRINGFIELD TWP (LUC county)

Location: OHIO TURNPIKE

1.1MI WEST OF EXIT 59

Resp A:

Insp

Resp B:

Inspector

Nelson,Tanner

Inspection Date 05/24/2022

Reviewer Hayes,Edmund

### **Inspector Comments - Deck and Approach**

#### **Deck**

The deck was raised to an 8 as only a minimal amount of cracking was observed in the deck underside, not exceeding 10% by area.

#### **Approach**

### **Inspector Comments - General Appraisal**

#### **Superstructure**

The superstructure was rated a 7 due to areas of rust and a deflecting bearing.

#### **Substructure**

The substructure was rated a 7 due to cracking throughout pier caps and abutment walls.

#### **Culvert**

### **Inspector Comments - Waterway**

#### **Waterway Adequacy**

#### **Channel**

#### **Scour Critical**