


Project 39-15-02 (PR-4 @ MP 216.1 to MP 221.26)

Exit 218 Notification Signage for Eastbound Traffic


Maintenance of Traffic Split 215.90

Message Board

Located at MP 206.9 (9 miles prior to split). The Message Board displays the 2-panel message shown below:



Panel 1 (2-Second display)



Panel 2 (2-Second display)

Mile Post 213.32 & 213.45

Left Side (4' by 4')



1st set of Notification Signs located 2 miles before the traffic split

Left Side (4' by 4')



Right Side (13' by 11')



Mile Post 214.32 & 214.45

Left Side (4' by 4')



2nd set of Notification Signs located 1 mile before the traffic split

Left Side (4' by 4')



Right Side (13' by 11')



Mile Post 214.82 & 214.95

Left Side (4' by 4')



3rd set of Notification Signs located 1/2 mile before the traffic split

Left Side (4' by 4')



Right Side (13' by 11')



Project 39-15-02 (PR-4 @ MP 216.1 to MP 221.26) Exit 218 Notification Signage for Eastbound Traffic

Mile Post 215.20 4th set of Notification Signs located 2000 Feet before the traffic split

Left Side (4' by 4')



Right Side (13' by 11')

