

Project 39-16-01 (PR-1 @ MP 107.3 to MP 112.45)

Exit 110 Notification Signage for Eastbound Traffic

Maintenance of Traffic Split 106.60

Message Board

Located at MP 100.7 (5.9 miles prior to split). The Message Board displays the 2-panel message shown below:

E	X	I	T		1	1	0
	S	R	-	4			
R	T		L	A	N	E	

Panel 1 (2-Second display)

6		M	I	L	E	S	
	A	H	E	A	D		

Panel 2 (2-Second display)


Mile Post 103.60

1st set of Notification Signs located 2 miles before the traffic split

Left Side (4' by 8.5')



Right Side (14' by 7')




Mile Post 104.62

2nd set of Notification Signs located 1 mile before the traffic split

Left Side (4' by 8.5')



Right Side (14' by 7')



Mile Post 105.23

3rd set of Notification Signs located 1/2 mile before the traffic split

Left Side (4' by 8.5')



Right Side (14' by 7')

