

OHIO TURNPIKE COMMISSION

ADDENDUM NO. 1


**BID INVITATION NO. 4173
A TWELVE MONTH SERVICE CONTRACT FOR THE INSPECTION, TESTING AND
REPAIR OF FIRE ALARM SYSTEMS, FIRE SPRINKLER SYSTEMS AND FIRE
SUPPRESSION/EXTINGUISHING SYSTEMS LOCATED IN VARIOUS COMMISSION
BUILDINGS**


OPENING DATE:
2:00 P.M. (E.S.T.), NOVEMBER 10, 2011

ATTENTION OF BIDDERS IS DIRECTED TO:

QUESTIONS AND ANSWERS THROUGH 2:00 P.M., OCTOBER 31, 2011

Issued by the Ohio Turnpike Commission October 31, 2011. Authorized by Daniel F. Castrigano, Interim Executive Director, and Kathleen Weiss, Director, Contracts Administration.


Daniel F. Castrigano
Date 10/31/11


Kathleen Weiss
Date 10/31/11

QUESTIONS AND ANSWERS THROUGH 2:00 P.M., OCTOBER 31, 2011:

Q#1 Is there a fire pump at any of these locations?

A#1 All of the locations with sprinkler protection have a fire pump, with the following exceptions: Administration Building, Communications Building, Vermilion Valley Service Plaza (pump is shared with Middle Ridge Service Plaza), and Portage Service Plaza (pump is shared with Brady's Leap Service Plaza).

Q#2 Is there any way to get an exact device count on these systems? Pulls, smokes etc...

A#2 Please see the attached spreadsheet that provides information on the approximate numbers of devices at each location.

Q#3 Is there a possibility of site surveys?

A#3 As indicated on Page 5a, paragraph 5 of the Bid Invitation, requests for scheduling site visitations can be arranged through the Commission's Purchasing Manager.

Q#4 Is there any possibility of getting a emailed copy of last years inspection reports?

A#4 Electronic copies of 2011 inspection reports are available in PDF format, upon request through the Commission's Purchasing Manager.

Receipt of Addendum No. 1, Invitation No. 4173 is hereby acknowledged:

(Firm Name) _____

(Signature) _____

(Printed Name) _____

(Date) _____

BIDDERS MUST RETURN THE ABOVE ACKNOWLEDGEMENT OF RECEIPT OF ADDENDUM NO. 1 WITH THEIR BID.

OHIO TURNPIKE COMMISSION

Total Facility Devices/Equipment per 2011 Fire Alarm Inspection Reports

Facility	Common Equipment				Initiating Devices				Notification Devices			Auxiliary		Total
	Control Panel	Power Supply	Annunc.	Battery	Pull Station	Smoke Smoke	Heat Detector	Duct Smoke Detector	Horn/Strobe	Strobe	Door Hold	Duct Det. Switch		
Kunkle Maintenance	1			2	6	1			8					18
Swanton Maintenance	1		1	2	8				8					20
Elmore Maintenance	1			2	9	4	1	6	17					40
Castalia maintenance	1		1	2	7				9					20
Amherst Maintenance	1			2	8			1	8					20
Boston Maintenance	1		1	2	5	1		3	8					21
Hiram Maintenance	1			2	14	1	1	1	18					39
Canfield Maintenance	1			2	6	1		1	8					19
Blue Heron Service Plaza	1	1	1	2	10	10	2	8	25	13	2		8	83
Wyandot Service Plaza	1	1	1	4	10	10	2	8	25	13	2		8	85
Erie Islands Service Plaza	1	2		6	8	10	8	10	23	12	2			82
Commodore Perry S. P.	1	3		8	8	10	8	10	24	14	2			88
Middle Ridge Service Plaza	2	1	1	6	12	14	4	8	35	14	4		8	109
Middle Ridge Pump House					3		2		2					7
Vermilion Valley Service Plaza	1	1	1	4	11	12	4	8	34	14	4			94
Great Lakes Service Plaza	1	0	0	2	7	4	2	8	20	16	2			62
Towpath Service Plaza	1	0	0	2	8	4	2	8	19	17	2			63
Portage Service Plaza	1	0	0	2	8	6	1	8	23	19	2			70
Brady's Leap Service Plaza	1	0	0	2	8	6	1	8	23	19	2			70
Administration Building	1	1	1	4	14	7		3	22	15	1		1	70
Communications Building	1	0	1	2	9	4	5	4	11	7			2	46
Total														1,126.00

* Device count for Indian Meadow and Tiffin River Service Plazas not available.